

# Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



#### WORK ORDER INFORMATION

Work Order Name: WO/80008KN0727/1
Work Order Type: Weatherization
Audit Name: 80008KN0727-Audit

#### **CLIENT INFORMATION**

Client Name: Address:

Client ID: 80008KN0727

Alt. Client ID: Knox

#### **AGENCY INFORMATION**

Agency: Knoxville/Knox County CAC Agency Phone: (865) 244-3080

Company Name & License Number:	 
Contractor's Signature:	

### **COMMENT**

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

House built in 1974

An EPA Certified Firm/Renovator is required.

Client Name:

Client ID: 80008KN0727
Alt. Client ID: Knox

Work Order (Bid Form)

Work Order Name: WO/80008KN0727/1 Report Run On: 5/6/2010 DOE Weatherization Assistant Version 8.6.0

Page 1 of 9

## Measures

i	Measure 1 Infilt	ration Redctn			Componen	ts			Inspected		
C	Replace broken panes on S1, N6, 20 sq. ft. in each.  •Reduce air infiltration with 13 air seals. Each air seal is equal to 100 cfms. It is the responsibility of the contractor to find the air leaks. This is best performed with a Blower Door. Contractor must meet or exceed the targeted #. A house must not be brought below 1500 cfm @ 50 pascals. No CHANGE ORDER for air seals below the targeted #.  "Open" Ring, Front Door, 3738 CFM @ 50 pascals. Target is 2438 CFM @ 50 PA  Seal all plumbing penetrations Location+Register Type^Initial (Pa) Bdrm1Supply1.9 Bdrm2Supply2.7 Bdrm3Supply1.7 Living RoomSupply9.3 Living RoomSupply9.3 Living RoomSupply5.6										
	ratoriorie	ларріуо.о			Estimated			Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total		
1	Miscellaneous Su	Infiltration Reduction	Each	13							
2	Labor	labor	Each	13	The state of the s						
<u>c</u>	Other Detail				3		,				
								over the second			
				Measur	e Sub Total:		:	Sub Total: [			
	Field Notes:										

	Measure 2 DWH	l Pipe Insulation			Componen	ts		i	Inspected	
C	omment									
					Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Insulation	DHW Pipe Insulation	Each	1						
		Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.								
2	Labor	DHW Pipe Insulation	Each	1						
(	Other Detail									
						G-20-00-0-2-11-0-0-0-0-0-0-0-0-0-0-0-0-0-				
				Measu	e Sub Total:			Sub Total:		
	Field Notes:								***************************************	

	Measure	3 F	loor	ns. R-19				Componer	nts F1			Inspected
C	comment	before Stan subfit (e.g. compare)	re ins dards loor al stave pressi	abor cost. Co talling insulat . Insulation i bove (paper s s for blanket ons. Refer t east Field G	ion. Conti s installed side agair s). Insula o Append	ractor to in I to maintanst st subfloo Ition to hav	stall us in peri r) inclu ve NO	sing Resnet manent con iding neces gaps, voids	Grade 1 tact with sary supp , or	the orts	ls	
								Estimated	<b>.</b>		Actual	
#	Material /	Laboi	r L	Description / Co	omment	Units	Qty	Unit Cost	Total	Qt	y Unit Cos	t Total
1	Insulatio	n		loor Insulation liberglass Batt	_	SqFt	2250	[				
2	Labor			loor Insulation	*	SqFt	2250	Attended				
C	Other Detai	ı										
F				-WASH								
							Measur	e Sub Total:		]	Sub Total:	
	Field Note	es:										-

Measure 4 DW	H Tank Insulation			Componen	ts		ı	nspected
Comment extend	pressure relief pipe as ne	eded						
	, ,		Estimated					
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Hot Water Equipn	n DHW Tank Insulation	Each	1					
	Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.					* ************************************		
2 Labor	DHW Tank Insulation	Each	1					
Other Detall								
					•			
					. 400-			
<b>S</b>			Measu	e Sub Total:			Sub Total:	
Field Notes:								

Alt. Client ID: Knox

Page 5 of 9

Measur	e 5 Sma	rt Thermostat			Component	s			Inspected
Commen	Thermos	ermostat. Must be equal stat (must submit equival client on operation of the	ent to Ho						
					Estimated			Actual	
# Material	/Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Heating	g Equipmen	Smart Thermostat	Each	1			] [		
		Includes labor cost. Must be equal to Honeywell's PRO 4000 Programmable Thermostat. Must be installed by a qualified technician. Must train homeowner on operation of thermostat. Refer to Appendix A- Standards for Weatherization Materials and South East Field Guide.							
2 Labor		Smart Thermostat	Each	1					
Other Deta	ail								
		1 11/4 11/2							
							1		]
1	J (			!	e Sub Total:		]	Sub Total:	
Field No	tes:							L	

C	attic spa access. soffit an insulatin silicone access a Grade 1	es labor cost. Contractor to ace showing depth of insu- Install baffles as needed d covering vent. Seal all ag. Seal around chimney or fire resistant foam. Instand weather strip with foat Standards. Refer to App s and Southeast Field Gu	ulation. Buto prevented to prevented to prevente to pr	uild inso t loose ps, and t meta fibergl Contrac	ulation dam ofill insulation d penetration I and high te ass batt sector to install	around a on from e ns in attic emperatu cured to a I using R	ttic ntering before re attic esnet	ı	
					Estimated	<u>!</u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Fiberglass - R-38	SqFt	2250					
2	Labor	Attic Insulation - Blown Fiberglass - R-38	SqFt	2250					
(	Other Detail								
				Measur	e Sub Total:	, ,	]	Sub Total:	
	Field Notes:			70.					

Components A1

Client ID: 80008KN0727
Alt. Client ID: Knox

Measure 6 Attic Ins. R-38

Report Run On: 5/6/2010

Inspected

	Measure 7 Furn			Componen		Inspected				
C	omment									
				Estimated			Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Heating Equipmen	Furnace Tuneup	Each	1			]			
		Includes labor cost. Must be completed by a licensed mechanical contractor. Must submit with invoice a completed tune up summary report.			, ,		,			
2	Labor	Furnace Tuneup	Each	1		THE TOTAL LE				
C	Other Detail									
		i								
	The second secon				Total Bases					
		· · · · · · · · · · · · · · · · · · ·		Measur	e Sub Total:		] ;	Sub Total:		
THE PARTY OF THE P	Field Notes:	7 - 10 AM - 1							and the second s	

	Measure 8 CO	nonitor is Needed			Componen	ts			Inspected
C	<b>Comment</b> Refer to Field Gu	Attachment A- Standard ide.	s for Wea	theriza	ition Materia	ls and Sc	utheas	st	
			Estimated			Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	CO monitor	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Each	1					
(	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:				100 500 have			7747.0644	
		Work Order Grand Total: Grand Total:							

Report Run On: 5/6/2010